Asbestos Hazard Emergency Response Act Three-Year Asbestos Re-Inspection and Management Plan Update

for Tashua Elementary School

For Compliance with
State of Connecticut Department of Public Health
Asbestos-Containing Material in Schools Regulation
(Sections 19a - 333-1 through 19a - 333-13)
and
EPA Asbestos Hazard Emergency Response Act
(Title 40 CFR, Part 763, Subpart E)

Trumbull Public Schools

Trumbull, Connecticut

February 2021



56 Quarry Road Trumbull, CT 06611



May 3, 2021

Mr. Paul Hendrickson Business Office – Business Administrator Trumbull Public Schools 6254 Main Street Trumbull, CT 06611

RE: Three-Year AHERA Asbestos Re-Inspection and Management Plan Update Re-Inspection Date: February 23, 2021
Tashua Elementary School
401 Stonehouse Road, Trumbull, CT
Fuss & O'Neill Project No. 20201149.A10

Dear Mr. Hendrickson:

Enclosed is the three-year AHERA Asbestos Re-Inspection and Management Plan Update report prepared by Fuss & O'Neill, Inc. at the Tashua Elementary School located at 401 Stonehouse Road in Trumbull, Connecticut (the "Site"). The inspection was performed for the Trumbull Public Schools (the "Client"). This report is an important document that must be kept on file at the school as well as at a central location where the Management Plans are maintained.

If you should have any questions regarding this report, please do not hesitate to contact me. Thank you for this opportunity to have served your environmental needs.

Sincerely,

56 Quarry Road Trumbull, CT 06611 † 203.374.3748 800.286.2469 Eduardo Miguel Marques Senior Environmental Analyst

EMM/nw

www.fando.com

Enclosure

California

f 203.374.4391

Connecticut

Maine

Massachusetts

New Hampshire

Rhode Island

Vermont

F:\P2020\1149\A10\Deliverables\Report\3 Year Re-Inspection 2021\Tashua\Tashua\ES_Final.docx



Table of Contents

Asbestos Hazard Emergency Response Act Three-Year Re-Inspection and Management Plan Update Tashua Elementary School

general	1.1 1.2 1.3	Duction
2	Buildi	ng and Mechanical System Description3
3	Three	Year Re-Inspection
	3.1	Re-Inspection Procedures
4	Re-In:	spection Report4
	4.1	Review of Existing Records
	4.2	Re-Inspection Summary
	4.3	Newly Identified or Re-sampled ACBM Materials
	4.4	Physical Assessment of ACBM
5	Mana	gement Plan Update8
	5.1	Recommended Response Actions
	5.2	Periodic Surveillance
	5.3	Preventive Measures
	5.4	Abatement (Removal) Cost Estimates
6	EPA A	ccreditation Requirements10
Appe	ndices	End of Report
APPEN	NDIX A	EXISTING RECORDS CHECKLIST
APPEN	NDIX B	RE-INSPECTION FORM 1A
APPEN	NDIX C	RE-INSPECTION FORM 2
APPEN	NDIX D	SAMPLE 6-MONTH PERIODIC SURVEILLANCE FORM
APPEN	NDIX E	PREVENTIVE MEASURES
APPEN	NDIX F	ASBESTOS INSPECTOR AND MANAGEMENT PLANNER STATE
		LICENSES AND EDA ACCREDITATIONS



1 Introduction

1.1 Background

The Clean Air Act required the United States Environmental Protection Agency (EPA) to develop standards to address the potential health risks associated with adverse effects of asbestos exposure as an indoor contaminant. In October 1986, the EPA promulgated the Asbestos Hazard Emergency Response Act (AHERA) located at Title 40 CFR, Part 763, Subpart E.

The AHERA regulations required that local education agencies (LEAs) conduct inspections of each school building that they lease, own, or otherwise use as a school building to identify friable (easily crumbled or crushed to powder by hand pressure) and non-friable asbestos-containing building materials (ACBM) locations. The original inspections were required to have been completed prior to October 12, 1988.

AHERA also requires that any building leased or acquired on or after October 12, 1988 that is to be used as a school building shall be inspected for friable and non-friable ACBM prior to use as a school building. In the event of an emergency use of a building that has not been inspected for ACBM, the building shall be inspected within 30 days after commencement of such use.

The regulatory requirements remain in effect for private or public school systems, a church-affiliated school of any denomination, a school dedicated to the education of children with special needs, or a charter school. In the State of Connecticut, the Department of Public Health (CTDPH) is responsible for AHERA regulation enforcement.

1.2 Local Education Agency (LEA) Responsibilities

- A. The LEA is responsible for compliance with the AHERA regulation. The following responsibilities must be followed:
 - The LEA must designate a person to ensure that all of the AHERA requirements are
 properly implemented. The Designated Person must receive adequate training to perform
 their duties.
 - The LEA must ensure that management plans are maintained in a central location, as well as at each facility, and such plans and records are available for inspection or review at all times.
 - 3. The LEA must inform all workers, building occupants or their legal representative in writing at least once per school year about asbestos-related activities, and the availability of the AHERA management plans for the school buildings.



- 4. The LEA must ensure proper accreditation for all persons who perform asbestos inspections, asbestos re-inspections, develop/update management plans, develop response actions, and perform required response actions including operations and maintenance (O&M) activities that may disturb asbestos.
- 5. The LEA must provide training for all custodial and maintenance staff who regularly perform building maintenance where ACBM are present. The training must be provided upon initial hire, as well as annual updates.
- The LEA must provide information (disclosure) to any workers who may perform work and may come into contact with asbestos in school buildings where ACBM or presumed ACBM are present.
- 7. The LEA must ensure that known ACBM or presumed ACBM are provided with warning labels in routine maintenance areas.
- 8. The LEA must ensure that periodic surveillance is performed at least once every six months, after management plan implementation, in all school buildings that it leases, owns, or otherwise uses that contains ACBM or presumed ACBM.
- 9. The LEA must ensure that once every three years, after a management plan is implemented, a Re-Inspection is performed at each school building that it leases owns or otherwise uses that contains ACBM or presumed ACBM.

Refer to above-mentioned regulation for full requirements and responsibilities.

1.3 Accreditation

A. Local Education Agency (LEA):

LEA:

Trumbull Public Schools

Address:

6254 Main Street

Trumbull, CT

Phone:

(203) 452-4300

B. Designated Person:

Designated Person:

Mr. Paul Hendrickson

Address:

6254 Main Street

Trumbull, CT

Phone:

(203) 452-4300



C. Asbestos Consultant:

Firm: Fuss & O'Neill, Inc. Address: 56 Quarry Road

Trumbull, CT

Phone: (203) 374-3748 Fax: (203) 374-4391

D. Asbestos Inspector:

Inspector: James B. Blum

CTDPH License #: 000841 Expiration Date: 11/30/2021

E. Asbestos Management Planner:

Planner: Eduardo Miguel Marques

CTDPH License #: 000201 Expiration: 2/28/2022

2 Building and Mechanical System Description

The original Tashua Elementary School is a one-story building and was reportedly constructed in 1965. The building contains approximately 52,000 square feet (SF) of total floor area. The building is heated by a gas-fired hot water and rooftop heating, ventilating and air conditioning (HVAC) units.

3 Three Year Re-Inspection

3.1 Re-Inspection Procedures

This three-year asbestos re-inspection was conducted in accordance with EPA requirements of the AHERA regulation, Title 40 CFR, Part 763, Section 763.85 (b).

On February 23, 2021, Fuss & O'Neill, Inc. (Fuss & O'Neill) representative Mr. James B. Blum performed the re-inspection.

- A. During the re-inspection, Fuss & O'Neill conducted the following required tasks:
 - 1. A visual re-inspection and reassessment of all known friable or assumed ACBM.
 - 2. A visual re-inspection of ACBM that was previously considered non-friable to determine if the present condition of the material has become friable.
 - 3. Identification and assessment of any newly-identified homogeneous area that contains friable ACBM since the last inspection or re-inspection.



4 Re-Inspection Report

4.1 Review of Existing Records

An important part of this AHERA re-inspection involved researching prior documentation that is required to be present at the school, as well as at the central recordkeeping location where management plans are stored.

Please see *Appendix A* for the checklist for existing records.

4.2 Re-Inspection Summary

The on-site portion of the re-inspection was documented on forms modeled after examples provided by the EPA and reviewed with the CTDPH. The first form, **Re-Inspection Form 1A**, identifies previous inspection data gathered during the initial AHERA inspection and subsequent re-inspection (see *Appendix B*). This form is useful to reference response actions (if any), which have been performed since the last inspection, as well as identifies the last known conditions of ACBM in the building. It additionally provides the inspector a "quick glance" reference when performing the re-inspection.

The second EPA form, **Re-Inspection Form 2**, was used to provide information and justification regarding <u>re-assessment of the ACBM</u> (see *Appendix C*). This form also provides response action recommendations, including a tentative schedule for completing response actions that recommend removal or repair.

No bulk samples were collected during this re-inspection.

Using EPA protocol and criteria, the following materials existing in Tashua Elementary School at the time of this three-year re-inspection have been determined and/or assumed to be **ACBM**. Please refer to the above-mentioned Re-Inspection Forms for specific locations of the materials.



Table 1
Asbestos-Containing Building Materials

	Tisbestos-Conta	uning Building Ma		
Material	Location	Reference	Asbestos Content	Notes
Blue 12"x12" Floor Tile & associated Adhesive	Rooms 1, 3, 5 - 8, 16, 19 - 22, Staff Lounge	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Green 12"x12" Floor Tile & associated Adhesive	Rooms 9, 10, 15, 17, TLC Room	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Gray with Multiple Colors Specks 12"x12" Floor Tile & associated Adhesive	Rooms 13, 14	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Gray with Tan Specks 12"x12" Floor Tile & associated Adhesive	Rooms 2, 12, 18, Reading	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Green with Green 12"x12" Floor Tile & associated Adhesive	Room 1A	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Gray with Green Specks 12"x12" Floor Tile & associated Adhesive	Room 4, Psychologist Office, Social Worker Office	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Light Blue 12"x12" Floor Tile & associated Adhesive	Stage Mechanical Room, Library, Computer Lab	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Blue Sheet Flooring & associated Adhesive	Room 11	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Tan Sheet Flooring & associated Adhesive	Nurse's Office	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Gray Sheet Flooring & associated Adhesive	Math Spec. Office	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Carpet Adhesive	Administration Offices, Room 1E,	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	



Material	Location	Reference	Asbestos Content	Notes
White with Tan 12"x12" Floor Tile & associated Adhesive	Cafeteria	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Blue 4" Cove Base & associated Adhesive	Rooms 1, 3, 5 - 8, 16, 19 - 22, Staff Lounge, Library, Computer Lab	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Green 4" Cove Base & associated Adhesive	Rooms 9, 10, 15, 17, TLC Room	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Gray 4" Cove Base & associated Adhesive	Rooms 2, 12, 18, Reading, Psychologist Office, Social Worker Office	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Cream 4" Cove Base & associated Adhesive	Cafeteria	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Green Rubber Flooring & associated Adhesive	Stage Stairways	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Pipe Insulation & Pipe Fitting Insulation	Custodial Closets, Above Suspended Ceiling Tiles Throughout Building	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Thinset & Grout associated with Ceramic Tile (multiple colors and sizes)	Boys' Bathrooms, Girls' Bathrooms, Faculty Bathrooms	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
2'x2' Suspended Ceiling Tiles (Multiple types: slots w/ pinholes, pinholes)	Boys' Bathrooms, Girls' Bathrooms, Faculty Bathrooms, Cafeteria, Hallways, Rooms 4, 6, 10, 16, 22, Music Room, Psychologist Office, Reading Room, Computer Lab, Media Center	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	



Material	Location	Reference	Asbestos Content	Notes
2'x4' Suspended Ceiling Tiles	Administration Offices, Rooms 1 - 3, 5, 7 -9, 11 - 15, 17 - 21, Kitchen, Social Worker Office	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Adhesive associated with Chalkboard and Tackboard	Rooms 1 - 11	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Gray Sink Undercoating	Rooms 1 - 22	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
White Sink Undercoating	TLC Room	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Tectum Ceiling	Custodial Closets, Custodians Office, Storage Closets	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	

Mr. Eduardo Miguel Marques reviewed the information obtained during this Re-Inspection. Mr. Marques is an EPA-accredited and CTDPH-licensed Asbestos Management Planner.

4.3 Newly Identified or Re-sampled ACBM Materials

During this re-inspection, no newly identified asbestos-containing materials or assumed ACBM were observed.

AHERA regulations pertain to interior identified or assumed ACBM and limited exterior ACBM. AHERA regulations do include ACBM located on exterior porticos, covered walkways, and mechanical equipment used to condition interior building air.

Any suspect material encountered during renovation/demolition/maintenance activities that is not specifically identified in the Asbestos Management Plan (AMP) as a non-ACM should be assumed to contain asbestos unless sample results indicate otherwise.

Additional Information:

- ACBM floor tile and associated mastics may exist below non-moveable objects such as cabinets.
 platforms, sheetrock walls, lockers, etc.;
- Samples of exterior building materials not covered under AHERA, such as caulking and glazing
 compounds, roofing materials and materials behind exterior walls and panels should be
 collected and analyzed to determine asbestos content prior to performing activities that would
 disturb them;



- Asbestos-containing vapor barriers and waterproofing materials may exist beneath wood floors, behind walls, exterior below ground surface foundations, etc.; and
- Subsurface cementitious pipe (i.e., asbestos cement pipe).

4.4 Physical Assessment of ACBM

During inspection, suspect ACBM were separated into three EPA categories. These categories are thermal system insulation (TSI), surfacing ACBM, and miscellaneous ACBM. TSI includes all materials used to prevent heat loss or gain or water condensation on mechanical systems. Examples of TSI are pipe and fitting insulations, boiler insulation, and duct insulation. Surfacing ACBM is commonly used for fireproofing, decorative, and acoustical applications. Miscellaneous materials include all ACBM not listed in TSI or surfacing, such as sheet flooring, vinyl asbestos flooring, ceiling tiles, and construction mastics/adhesives.

Finally, ACBM were quantified in linear and/or square feet, depending on the nature of the material.

The ACBM identified during the inspection and still remaining in the school were re-assessed using the CTDPH and AHERA guidelines for assessment of ACBM. The following assessment categories are listed:

- 1. Damaged or significantly damaged TSI ACBM
- 2. Damaged friable surfacing ACBM
- 3. Significantly damaged friable surfacing ACBM
- 4. Damaged or significantly damaged friable miscellaneous ACBM
- 5. ACBM with potential for damage
- 6. ACBM with potential for significant damage
- 7. Any remaining friable ACBM or friable suspected ACBM

Material locations, assessments, and recommended response actions are listed in the Re-Inspection forms.

5 Management Plan Update

5.1 Recommended Response Actions

Based on the inspection report, physical walk-through inspection, and existing ACBM conditions, the following response actions are recommended:

- 1. Removal Not Applicable
- 2. Repair Not Applicable
- 3. Enclosure Not Applicable
- 4. Encapsulation Not Applicable
- 5. Operations and Maintenance (O & M) All remaining ACBM.



It should be noted that only ACBM with assessments of 1 or 2 are recommended for removal or repair. The remaining ACBM should be included in the O & M Program. The condition of these ACBM will be monitored until all of the ACBM have been completely removed from the building. A successful O & M Program includes the following elements:

- A. <u>Cleaning</u>: All areas of the school where friable ACBM or assumed friable ACBM are present should be cleaned at least once after completion of the initial inspection. Additional cleaning may be necessary if the Management Planner makes a written recommendation indicating the methods and frequency of such cleaning.
- B. O & M Activities: The LEA shall ensure that the procedures described below are followed to protect building occupants from O & M activities that may disturb known or assumed ACBM:
 - 1. Restrict entry into the area either by physically isolating or by scheduling.
 - 2. Post asbestos warning signs to prevent entry by unauthorized persons.
 - 3. Deactivate or temporarily shut off or divert the air-handling system to the area.
 - 4. Use proper work practices and engineering controls, such as wet methods, protective clothing, High Efficiency Particulate Air (HEPA) vacuums, mini-enclosures/glove bags, etc. to inhibit fiber migration.
 - 5. Place asbestos debris and other contaminated materials into a sealed, leak-tight container for disposal.
- C. <u>Minor Fiber Release Episode</u>: The LEA shall ensure that the procedures described below are followed in the event of a minor fiber release episode (i.e., disturbance of less than or equal to 3 linear/square feet of friable ACBM):
 - 1. Saturate the debris using wet method.
 - 2. Place the debris in a sealed, leak-tight container and clean the area.
 - 3. Repair the area of damaged ACBM with materials such as asbestos-free spackling, plaster or insulation or seal with an encapsulant.
- D. <u>Major Fiber Release Episode</u>: The LEA shall ensure that the procedures described below are followed in the event of a major fiber release episode (i.e., disturbance of greater than 3 linear/square feet of friable ACBM):
 - 1. Restrict entry into the area and post asbestos warning signs.
 - 2. Deactivate or temporarily shut off or divert the air handling system from the area to prevent fiber migration.
 - 3. The response action for any major fiber release episode must be prepared by EPA-accredited Asbestos Project Designers and conducted by EPA-accredited personnel.
 - 4. The LEA shall notify the CTDPH of any major fiber release episode within twenty-four hours of its occurrence and, if necessary, provide written notification as required by applicable federal and/or state regulations.



5.2 Periodic Surveillance

At least once every six months after an AMP is implemented, the LEA will conduct periodic surveillance in the school that contains ACBM or assumed ACBM. The person conducting periodic surveillance will visually inspect all areas in the school that where ACBM have been identified in the AMP, record the date of surveillance, their name, any changes in the ACBM condition and submit the record to the LEA Designated Person for inclusion in the AMP.

Please see *Appendix D* for the sample Periodic Surveillance Form that may be used for conducting periodic surveillance.

5.3 Preventive Measures

The LEA shall institute appropriate preventive measures to eliminate the reasonable likelihood that ACBM will become damaged, deteriorated, or delaminated.

Please see *Appendix E* for preventive measures designed for various types of ACBM that may exist in the school.

5.4 Abatement (Removal) Cost Estimates

At the time of the February 23, 2021 re-inspection, no materials were observed to be damaged (other than O&M repairs); therefore, estimated abatement costs have not been provided.

6 EPA Accreditation Requirements

The EPA accreditations and the CTDPH Asbestos Inspector for James B. Blum and Eduardo Miguel Marques are provided in *Appendix F*.

Report prepared by Senior Environmental Technician James B. Blum, CMC.

Reviewed by:

Eduardo Miguel Marques

Senior Environmental Analyst

Jared D. Smith, CSP Senior Project Manager



Appendix A

Existing Records Checklist



Existing Records Checklist

Local Education Agency (LEA): Trumbull Public Schools

6254 Main Street Trumbull, CT 06611

School Building: <u>Tashua Elementary School</u>

The following documentation is required to be present in both the LEA's office, as well as in a centralized location in the school administrative office. The information included in this checklist will be verified to be present and complete as part of three-year Re-Inspection.

		LOC	ATION
	DOCUMENTATION	School	LEA Office
1	Original AHERA Operations and Maintenance Plan/Inspection Report	No	No
2	Three Year Re-Inspection (First and All Subsequent Inspections)	No	Limited*
3	Parents and Teachers Notifications (Annually Since Last Re- Inspection)	Yes	Yes
4	Designated Person Identification and Proper Training (Person Must Be Named and Have Appropriate Training)	No	No
5	Designated Person Periodic Surveillance (Once Every Six Months)	No	Limited*
6	Maintenance Staff Awareness Training Records	No	No
7	Outside Vendor Awareness Notification	No	No
8	Asbestos Warning Signs and Labels (Required Posting in Boiler Rooms and Mechanical Spaces Only)	N/A	N/A
9	Response Action Records (Includes Any Abatement Conducted Since Last 3-Year Re-Inspection)	No	No

Comments: Items marked "No" indicate not present/available at the time of this inspection.

*Note: LEA office found to contain only records of 2015 3-year re-inspection, and 6 month surveillance conducted in 2015. Information associated with abatement work reportedly performed at the Site was not present.

Inspector (LEA Office): <u>James B. Blum</u> Date: <u>February 23, 2021</u>

Inspector (School): <u>James B. Blum</u> Date: <u>February 23, 2021</u>



Appendix B

Re-Inspection Form 1A



Re-Inspection Form 1(A) - List of Identified ACBM

School: <u>Tashua Elementary School</u> Address: <u>401 Stonehouse Road, Trumbull, CT</u> Date(s) of Original Inspection: <u>Unknown</u>
Date(s) of Subsequent Re-Inspections: <u>2015, 2021</u>

Homogeneous Material			Material	T	I		Response Actions
Sample Number	Asbestos Content	Material Description	Category	Friability	Assessment Category (1-7)	Recorded Locations	Taken/Renovations/Other Comments
N/A	Assumed	Blue 12"x12" Floor Tile & associated Adhesive	Misc.	NF	5	Rooms 1, 3, 5 - 8, 16, 19 - 22, Staff Lounge	
N/A	Assumed	Green 12"x12" Floor Tile & associated Adhesive	Misc.	NF	5	Rooms 9, 10, 15, 17, TLC Room	
N/A Assumed Gray with Multiple Colors Specks 12"x12" Floor Tile & associated Adhesive		Misc.	NF	5	Rooms 13, 14		
N/A	Assumed	Gray with Tan Specks 12"x12" Floor Tile & associated Adhesive	Misc.	NF	5	Rooms 2, 12, 18, Reading	
N/A	Assumed	Green with Green 12"x12" Floor Tile & associated Adhesive	Misc.	NF	5	Room IA	
N/A	Gray with Green		Misc.	NF _ģ	5	Room 4, Psychologist Office, Social Worker Office	
N/A	N/A Assumed Floor Tile & associated Adhesive		Misc.	NF	5	Stage Mechanical Room, Library, Computer Lab	
N/A	Assumed	Blue Sheet Flooring & associated Adhesive	Misc.	NF	5	Room 11	
N/A	Assumed	Tan Sheet Flooring & associated Adhesive	Misc.	NF	5	Nurse's Office	
N/A	Assumed	Gray Sheet Flooring & associated Adhesive	Misc.	NF	5	Math Spec. Office	
N/A	Assumed	Carpet Adhesive	Misc.	NF	5	Administration Offices, Room 1E,	
N/A	Assumed	White with Tan 12"x12" Floor Tile & associated Adhesive	Mise.	NF	5	Cafeteria	



Homogeneous Material		Material		Assessment		Response Actions	
Sample Number	Asbestos Content	Material Description	Category	Friability	Category (1-7)	Recorded Locations	Taken/Renovations/Other Comments
N/A	Assumed	Blue 4" Cove Base & associated Adhesive	Misc.	NF	5	Rooms 1, 3, 5 - 8, 16, 19 - 22, Staff Lounge, Library, Computer Lab	
N/A	Assumed	Green 4" Cove Base & associated Adhesive	Misc.	NF	5	Rooms 9, 10, 15, 17, TLC Room	
N/A	N/A Assumed Gray 4" Cove Base & associated Adhesive		Misc.	NF	5	Rooms 2, 12, 18, Reading, Psychologist Office, Social Worker Office	
N/A	Assumed	Cream 4" Cove Base & associated Adhesive	Misc.	NF	5	Cafeteria	
N/A	N/A Assumed Green Rubber Floorin & associated Adhesive		Misc.	NF	5	Stage Stairways	
N/A	Assumed	Pipe Insulation & Pipe Fitting Insulation	TSI	F	5	Custodial Closets, Above Suspended Ceiling Tiles Throughout Building	<u> </u>
N/A	Thinset & Grout		Misc.	NF	5	Boys' Bathrooms, Girls' Bathrooms, Faculty Bathrooms	
N/A	N/A Assumed 2'x2' Suspended Ceiling Tiles (Multiple types: slots w/ pinholes, pinholes)		Misc.	NF	5	Boys' Bathrooms, Girls' Bathrooms, Faculty Bathrooms, Cafeteria, Hallways, Rooms 4, 6, 10, 16, 22, Muisic Room, Psychologist Office, Reading Room, Computer Lab, Media Center	
N/A	Assumed	2'x4' Suspended Ceiling Tiles	Misc.	NF	5	Administration Offices, Rooms 1 - 3, 5, 7 -9, 11 - 15, 17 - 21, Kitchen, Social Worker Office	
N/A	N/A Assumed with Chalkboard and Tackboard		Misc.	NF	5	Rooms 1 - 11	
N/A	Assumed	Gray Sink Undercoating	Misc.	NF	5	Rooms 1 - 22	
N/A	Assumed	White Sink Undercoating	Misc.	NF	5	TLC Room	***************************************
N/A	Assumed	Tectum Ceiling	Misc.	NF	5	Custodial Closets, Custodians Office, Storage Closets	



Homogeneous Material			Material		Assessment		Response Actions
Sample Number	Asbestos Content	Material Description	Category	Friability	Category (1-7)	Recorded Locations	Taken/Renovations/Other Comments
N/A	Assumed	9"x9" Floor Tile & associated Mastic	N/A	N/A	N/A	Throughout Building	Material has been reported to have been abated over several phases after 2015. Materials were not observed during this re-inspection

Information abstracted by: <u>James B. Blum</u>

Date: February 23, 2021

Material Category: TSI = Thermal System Insulation, S = Surfacing, M = Miscellaneous

LF = Linear Feet; SF = Square Fee

Friability: F = Friable, NF = Non-Friable

AHERA Assessment Categories: 1 = Damaged or significantly damaged TSI ACBM; 2 = Damaged friable surfacing ACBM; 3 = Significantly damaged friable surfacing ACBM; 4 = Damaged or significantly damaged friable miscellaneous ACBM; 5 = ACBM with potential for damage; 6 = ACBM with potential for significant damage; 7 = Any remaining friable ACBM or friable suspected ACBM



Appendix C

Re-Inspection Form 2



School:

<u>Tashua Elementary School</u> Date of Re-Inspection: February 23, 2021

Homogeneous Material:

Blue 12"x12" Floor Tile & associated Adhesive Sample ID:

А	CBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 1, 3, 5 - 8, 16, 19 - 22, Staff Lounge	NF	5,000 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll-	ected?	No			Date of Management Planner Review:	4/22/2021
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	شمار	Garge J.Co.	y 5		Management Planner Signature:	Edward Mych May -
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022
I, the LEA's Designated Horson, have read a Date:	and understoo	od the recommen	dations made abov	e: Dant B	hendrichem	



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Green 12"x12" Floor Tile & associated Adhesive

Homogeneous Material:

Sample ID:

 N/Λ

Δ.	CBM RE-IN	MANAGEMENT PLANNER I	RECOMMENDATIONS			
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 9, 10, 15, 17, TLC Room	NF	2,200 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	ected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m	·····		Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	ر مناسب	ang flor			Management Planner Signature:	ander Myd Myd-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021			,004.com	Expiration Date:	2/28/2022
I, the LEA's Someted Present have read a	ınd understoo	od the recommen	dations made abov	· / / / / / / / / / / / / / / / / / / /	Hundridson.	



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Homogeneous Material: Gray with Floor Tile (

Gray with Multiple Colors Specks 12"x12" Floor Tile & associated Adhesive

Sample ID:

 N/Δ

	ACBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 13, 14	NF	800 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM col	lected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	j.	lange filos		Management Planner Signature:	county Wight Alley -	
Accreditation #/State:	000841/CT		1		Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Homogeneous Material:

Gray with Tan Specks 12"x12" Floor Tile & associated Adhesive

Sample ID:

A	CBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 2, 12, 18, Reading	NF	1,600 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	ected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	parin.	ang p			Management Planner Signature:	ands Olyd Myst-
Accreditation #/State:	000841/CT	Accreditation #/State:	000201/CT			
Expiration Date:	11/30/2021			No.	Expiration Date:	2/28/2022



School: Tashua Elementary School Date of Re-Inspection: February 23, 2021

Green with Green 12"x12" Floor Tile & associated Adhesive

Sample ID: Homogeneous Material: N/A

	ACBM RE-IN	SPECTION FIN	DINGS		MANAGEMENT PLANNER RECOMMENDATIONS		
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed	
Room IA	NF	250 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing	
Were additional samples of this ACBM col	lected?	No			Date of Management Planner Review:	4/22/202	
Inspector's Name:	James B. Blu	ım			Management Planner Name:	Eduardo Miguel Marques	
Inspector Signature:	ا مستحد	langs film			Management Planner Signature:	ands Myd Myft-	
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT	
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022	



School: Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Gray with Green Specks 12"x12" Floor Tile & associated Adhesive Sample ID: Homogeneous Material: N/A

	ACBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Room 4, Psychologist Office, Social Worker Office	NF	1,200 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM col	lected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	j	George John			Management Planner Signature:	Edward Might MAJD-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



School: Tashua Elementary School Date of Re-Inspection: February 23, 2021

Light Blue 12"x12" Floor Tile & associated Adhesive Homogeneous Material: Sample ID: N/A

A	CBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Stage Mechanical Room, Library, Computer Lab	NF	1,000 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	ected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	<i>j.</i>	lasays-Jiller			Management Planner Signature:	ands Phyl May)-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Homogeneous Material:

Blue Sheet Flooring & associated Adhesive Sample ID:

А	CBM RE-IN	MANAGEMENT PLANNER	RECOMMENDATIONS			
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Room 11	NF	350 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll-	ected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	/	angs film			Management Planner Signature:	Elinho Might Might
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date: I, the LEA's Designated Person, have read a Date:	11/30/2021				Expiration Date:	2/28/2022



Schools

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Homogeneous Material:

Tan Sheet Flooring & associated Adhesive Sample ID:

4	CBM RE-IN	MANAGEMENT PLANNER I	RECOMMENDATIONS			
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Nurse's Office	NF	400 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	ected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:		anger film			Management Planner Signature:	elade Myd Myf-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022





School: <u>Tashua Elementary School</u> Date of Re-Inspection: February 23, 2021

Homogeneous Material: <u>Gray Sheet Flooring & asscoiated Adhesive</u> Sample ID: <u>N/A</u>

А	CBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Math Spec. Office	NF	350 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM colle	ected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	<i>j</i> /	Cargo His			Management Planner Signature:	security Might Might
Accreditation #/State:	000841/CT				Accreditation #/State:	<u>000201/CT</u>
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Homogeneous Material:

Camet Adhesive

Sample ID:

	ACBM RE-IN	MANAGEMENT PLANNER	RECOMMENDATIONS			
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Administration Offices, Room 1E,	NF	1,000 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM col	lected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Bli	ım			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	ji.	Samuel Herr			Management Planner Signature:	Elmila Mijd Mijd
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Homogeneous Material:

White with Tan 12"x12" Floor Tile & associated Adhesive

Sample ID:

4	ACBM RE-IN	MANAGEMENT PLANNER I	RECOMMENDATIONS			
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Cafereria	NF	2,000 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	ected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	ر منسر	argo Julio			Management Planner Signature:	ands Myd Myd-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Homogeneous Material:

Blue 4" Cove Base & associated Adhesive Sample ID:

 N/Δ

A	CBM RE-IN	MANAGEMENT PLANNER I	RECOMMENDATIONS			
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 1, 3, 5 - 8, 16, 19 - 22, Staff Lounge, Library, Computer Lab	NF	800 LF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	ected?	No			Date of Management Planner Review:	4/22/202
inspector's Name:	James B. Blu	un			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	<i></i>	ange fler			Management Planner Signature:	Elander Might Might
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Homogeneous Material:

Green 4" Cove Base & associated Adhesive

N/A

ACBM RE-INSPECTION FINDINGS MANAGEMENT PLANNER RECOMMENDATIONS ACBM Location(s) by Assessment Estimated Recommended Response Friability Physical Description Date Action Completed Category Quantity Category Action(s) Maintain under O & M Plan, ACBM with potential for Rooms 9, 10, 15, 17, TLC Room NF 800 LF Recommend sampling to determine Ongoing asbestos content prior to disturbance 4/22/2021 Were additional samples of this ACBM collected? Date of Management Planner Review: Inspector's Name: James B. Blum Management Planner Name: Eduardo Miguel Marques similar Might Map -Management Planner Signature: Inspector Signature: Accreditation #/State: 000841/CT Accreditation #/State: 000201/CT Expiration Date: 11/30/2021 2/28/2022 1, the LEA's Designated Persor Date: 5, 14, 7 ave read and understood the recommendations made above:

Sample ID:



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Homogeneous Material:

Gray 4" Cove Base & associated Adhesive Sample ID:

	ACBM RE-IN	SPECTION FIN	DINGS		MANAGEMENT PLANNER RECOMMENDATIONS		
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed	
Rooms 2, 12, 18, Reading, Psychologist Office, Social Worker Office	NF	800 LF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing	
Were additional samples of this ACBM coll	ected?	No			Date of Management Planner Review:	4/22/202	
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques	
Inspector Signature:	المراجعة المراجعة	ange Her			Management Planner Signature:	stude Wid Nagt-	
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT	
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022	



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Homogeneous Material:

Cream 4" Cove Base & associated Adhesive Sample ID:

<i>A</i>	CBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Cafeteria	NF	200 LF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	ected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	شر	ang plac			Management Planner Signature:	einde Myd Myf-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Homogeneous Material:

Green Rubber Flooring & associated Adhesive Sample ID:

	ACBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Stage Stairways	NF 60 SF 5 ACBM with potential for damage				Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM col	lected?		Date of Management Planner Review:	4/22/202		
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	/	ary His			Management Planner Signature:	Stude Wed Nyd Nyf-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Homogeneous Material:

Pipe Insulation & Pipe Fitting Insulation

Sample ID:

	ACBM RE-IN	ISPECTION FIN	DINGS		MANAGEMENT PLANNER RECOMMENDATIONS		
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed	
Custodial Closets, Above Suspended Ceiling Tiles Throughout Building	F Not Quantified 5 ACBM with potential for damage				Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing	
Vere additional samples of this ACBM col	lected?	No			Date of Management Planner Review:	4/22/202	
nspector's Name:	James B. Bh	ım			Management Planner Name:	Eduardo Miguel Marques	
nspector Signature:	<i>)</i>	latingto flish			Management Planner Signature:	Stanler Might MAJO-	
secreditation #/State:	000841/CT				Accreditation #/State:	000201/CT	
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022	



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Thinset & Grout associated with Ceramic Tile (multiple colors and sizes) Sample ID:

Homogeneous Material: (multiple colors and sizes)

ID:

 N/Λ

	ACBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Boys' Bathrooms, Girls' Bathrooms, Faculty Bathrooms	NF 800 SF 5 ACBM with potential for damage				Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	lected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:) ³²	aporto Price.			Management Planner Signature:	and Myd Mgf-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Homogeneous Material:

2'x2' Suspended Ceiling Tiles (Multiple types: slots w/ pinholes, pinholes) Sample ID:

A	CBM RE-IN	SPECTION FIN	DINGS		MANAGEMENT PLANNER RECOMMENDATIONS		
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed	
Boys' Bathrooms, Girls' Bathrooms, Faculty Bathrooms, Cafeteria, Hallways, Rooms 4, 6, 10, 16, 22, Muisic Room, Psychologist Office, Reading Room, Computer Lab, Media Center	NF	3,000 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disrurbance	Ongoing	
Were additional samples of this ACBM colle	ected?		Date of Management Planner Review:	4/22/2021			
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques	
Inspector Signature: June John					Management Planner Signature:	ands Mil Mill	
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT	
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022	



Date of Re-Inspection: February 23, 2021 School: Tashua Elementary School

2'x4' Suspended Ceiling Tiles Sample ID: Homogeneous Material: N/A

A	CBM RE-IN	ISPECTION FIN	DINGS		MANAGEMENT PLANNER RECOMMENDATIONS		
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed	
Administration Offices, Rooms 1 - 3, 5, 7 - 9, 11 - 15, 17 - 21, Kitchen, Social Worker Office	ACBM with potential for				Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing	
Were additional samples of this ACBM colle	ected?		Date of Management Planner Review:	4/22/202			
Inspector's Name:	James B. Blu	ım			Management Planner Name:	Eduardo Miguel Marques	
Inspector Signature:). J	lange-files			Management Planner Signature:	ands Myd Myd-	
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT	
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022	



Tashua Elementary School Date of Re-Inspection: February 23, 2021 School:

Adhesive associated with Chalkboard and Tackboard Homogeneous Material: Sample ID: N/A

A	CBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms I - 11	NF 100 SF 5 ACBM with potential for damage				Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	ected?	Date of Management Planner Review:	4/22/203			
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	j.	lange Jelin			Management Planner Signature:	stude Alfiel Alleft-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Homogeneous Material:

Gray Sink Undercoating

Sample ID:

A	CBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 1 - 22	NF	22 EA	5	ACBM with potential for damage	Not Regulated By AHERA; For Informational Purposes Only. Material Must Be Managed/Disposed Of As ACM Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	ected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	ım			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	1	arge His			Management Planner Signature:	ands Myd Myd-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



School: <u>Tashua Elementary School</u> Date of Re-Inspection: February 23, 2021

Homogeneous Material: White Sink Undercoating Sample ID: N/A

A	CBM RE-IN		MANAGEMENT PLANNER RECOMMENDATIONS			
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
TLC Room	NF	I Ea	5	ACBM with potential for damage	Not Regulated By AHERA; For Informational Purposes Only. Material Must Be Managed/Disposed Of As ACM Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll-	ected?	Date of Management Planner Review:	4/22/2021			
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	j.	ary Hi-			Management Planner Signature:	einde Myd Myf-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022

Frank B Handrich



School:

Tashua Elementary School

Date of Re-Inspection: February 23, 2021

Homogeneous Material:

Tectum Ceiling

Sample ID:

 N/Δ

A	CBM RE-IN	SPECTION FIN	DINGS		MANAGEMENT PLANNER I	RECOMMENDATIONS
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Custodial Closets, Custodians Office, Storage Closets	NF 800 SF 5 ACBM with potential for damage				Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	ected?	Date of Management Planner Review:	4/22/2021			
Inspector's Name:	James B. Blu	ım			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:		Carrys John			Management Planner Signature:	ands Myd Myf-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022
I, the LEA's Designated Person, have read a	and understoo	od the recommer	ndations made abov	Paul 15 Ho	ndrichem	



Appendix D

Sample 6-Month Periodic Surveillance Form



Sample 6-Month Periodic Surveillance Form

Local Education Agency (LEA): Facility Address: Date of Surveillance:

Trambull Public Schools
Tashua Elementary School, 401 Stonehouse Road, Trumbull, CT

Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
Blue 12"x12" Floor Tile & associated Adhesive	Rooms 1, 3, 5 - 8, 16, 19 - 22, Staff Lounge					
Green 12"x12" Floor Tile & associated Adhesive	Rooms 9, 10, 15, 17, TLC Room					
Gray with Multiple Colors Specks 12"x12" Floor Tile & associated Adhesive	Rooms 13, 14					
Gray with Tan Specks 12"x12" Floor Tile & associated Adhesive	Rooms 2, 12, 18, Reading					
Green with Green 12"x12" Floor Tile & associated Adhesive	Room 1A					
Gray with Green Specks 12"x12" Floor Tile & associated Adhesive	Room 4, Psychologist Office, Social Worker Office					
Light Blue 12"x12" Floor Tile & associated Adhesive	Stage Mechanical Room, Library, Computer Lab					
Blue Sheet Flooring & associated Adhesive	Room 11					
Tan Sheet Flooring & associated Adhesive	Nurse's Office					
Gray Sheet Flooring & associated Adhesive	Math Spec. Office					
Carpet Adhesive	Administration Offices, Room 1E,					
White with Tan 12"x12" Floor Tile & associated Adhesive	Cafeteria					
Blue 4" Cove Base & associated Adhesive	Rooms 1, 3, 5 - 8, 16, 19 - 22, Staff Lounge, Library, Computer Lab					
Green 4" Cove Base & associated Adhesive	Rooms 9, 10, 15, 17, TLC Room					
Gray 4" Cove Base & associated Adhesive	Rooms 2, 12, 18, Reading, Psychologist Office, Social Worker Office					
Cream 4" Cove Base & associated Adhesive	Cafeteria					
Green Rubber Flooring & associated Adhesive	Stage Stairways					
Pipe Insulation & Pipe Fitting Insulation	Custodial Closers, Above Suspended Ceiling Tiles Throughout Building					
Thinset & Grout associated with Ceramic Tile (multiple colors and sizes)	Boys' Bathrooms, Girls' Bathrooms, Faculty Bathrooms					-
2'x2' Suspended Ceiling Tiles (Multiple types: slots w/ pinholes, pinholes)	Boys' Bathrooms, Girls' Bathrooms, Faculty Bathrooms, Cafetraa, Hallways, Rooms 1, 6, 10, 16, 22, Music Room, Psychologist Office, Reading Room, Computer Lab, Media Center					



Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
2'x4' Suspended Ceiling Tiles	Administration Offices, Rooms 1 - 3, 5, 7-9, 11 - 15, 17 - 21, Kitchen, Social Worker Office					
Adhesive assocaited with Chalkboard and Tackboard	Rooms 1 - 11					
Gray Sink Undercoating	Rooms 1 - 22					
White Sink Undercoating	TLC Room					
Techim Coiling	Custodial Closets, Custodians Office, Storage Closets					

Conditions: D = Damaged; F = Fair; G = Good; IA = Inaccessible; N/A = Not Applicable; SD = Significant D	Jamage;	
SF = Square Feet		
Surveillance conducted by:		
(print name)	(signature)	
I, the LEA's Designated Person, have read and understood the findings noted above:		
Date:		



Appendix E

Preventive Measures



Preventive Measures for Various Asbestos-Containing Building Materials

A. Surfacing Materials

"Surfacing Materials" means materials in a school building that are applied by spray, trowel, or otherwise applied to surfaces. These include sprayed-applied fireproofing materials on structural members, ceiling and wall plasters, or other materials applied to surfaces for acoustical, fireproofing, or other purposes.

Surfacing Materials are generally considered friable and can release asbestos fibers if damaged by impact, air erosion, vibration, and/or water intrusion. When properly implemented, the following procedures will reduce the potential for fiber release:

1. Sprayed-Applied Fireproofing

- a) Identify the materials and post warning signs on the laid-in or glued-in ceiling tile. If the decking is not covered, place the sign on the wall.
- b) Maintain the materials in intact state and undamaged condition. During winter, pigeons, squirrels and other rodents tend to roost in boiler/machine rooms and dislodge sprayed-applied fireproofing on the decking. Prevent such possibilities.
- c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, enclosure is a temporary solution. Encapsulation of damaged sprayed-on fireproofing material is not recommended.
- d) Train the custodial people who are responsible for care and maintenance of surfacing materials. <u>Please note that the repair/removal can only be performed by a licensed abatement contractor.</u>

2. <u>Ceiling and Wall Plasters</u>

- a) Identify the materials and post asbestos warning signs.
- b) Maintain the materials in intact state and undamaged condition. Avoid storing/stacking on/near the materials to reduce contact damage.
- c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, repair or enclosure is a temporary solution.
- Train the custodial people who are responsible for care and maintenance of surfacing materials.

B. Thermal System Insulation (TSI)

"Thermal System Insulation (TSI)" means insulating materials applied to pipes, pipe fittings, boilers, breechings, tanks, ducts, or other components to prevent process heat loss or gain, water condensation, or for other purposes (e.g., fire door insulation core).



TSI are generally considered friable ACBM. This means they can be easily damaged, increasing the potential for fiber release. When properly implemented, the following procedures will reduce the potential for fiber release:

1. <u>Boiler and Breeching Insulation</u>

- a) Identify the locations and label the boiler. Warning signs should be posted outside the boiler room.
- b) Reduce the likelihood of fiber release by ensuring that the insulation is not damaged. Avoid storing/stacking on/near the boiler to reduce contact damage.
- c) Maintain the insulation in intact state and undamaged condition. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
- d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Pipe, Pipe Fitting, Tank, Duct & Breeching Insulations

- a) Identify the locations and label the materials. Warning signs should be posted outside of rooms that have TSI materials.
- b) Reduce the likelihood of fiber release by ensuring that the materials are not damaged. Avoid storing/stacking near the materials to reduce contact damage.
- c) Maintain all TSI materials in intact state and undamaged condition. Inspect the protective jackets for damage. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
- d) Train the custodial people who are responsible for care and maintenance of TSI.

 Please note that the repair/removal can only be performed by a licensed abatement contractor.

C. Miscellaneous Materials

"Miscellaneous Materials" are the other ACBM in a school building that are not categorized as Surfacing Materials or TSI. These include floor tiles, floor tile and carpet mastics, gypsum wallboard and joint compound, ceiling tiles, glue daubs, asbestos cement panels, cove base and associated glue, window/door caulking and glazing compounds, etc. The following maintenance procedures are recommended for these materials:

1. <u>Vinyl Asbestos Floor Tiles (VAT)</u>

Vinyl Asbestos Floor Tiles (VAT) are considered non-friable, however routine maintenance procedures such as spray-buffing, burnishing, wet scrubbing, and stripping can generate asbestos fibers. Following procedures, when properly implemented, will reduce the potential of fiber release:



- a) Do not sand, grind, or abrade the tiles. Stripping of VAT should be done as infrequently as possible. When stripping becomes necessary, follow the appropriate work practices. <u>Never perform dry stripping</u>.
- b) During spray-buffing or burnishing the floor, operate the machine at the lowest workable speed and use the least abrasive pad. Use a wet mop for routine cleaning whenever possible.
- c) Routinely check whether chair and desk glides are in good condition and replace when necessary. Worn glides can gouge the floor and cause fiber release.
- d) Place carpets/floor mats in all entrances to reduce abrasion of floor tiles by sand and pebbles. During winter, have parking lots and walkways swept to the extent possible to avoid the tracking of salt and ice-melting compounds into the school by the students.
- e) Train the custodial people who are responsible for care and maintenance of VAT. <u>Please note that the repair/removal can only be performed by a licensed abatement contractor.</u>

2. Wallboard and Joint Compound Assembly

- a) Since a number of different homogeneous assemblies may exist in a building, sheetrock/joint compound must be assumed to be ACBM unless sample results prove otherwise. If any specific areas are going to be disturbed, samples of the material in that area should be collected and analyzed.
- b) Reduce the likelihood of fiber release by avoiding cutting or drilling holes through the sheetrock panels.

3. Ceiling Tile and Glue Daubs

- a) Reduce the likelihood of fiber release by limiting access to the space above the ceiling tiles. Maintain the ceiling tiles in undamaged condition. Replace any damaged or water-stained tile.
- b) If the ceiling tiles are non-asbestos, collect samples and analyze the glue daubs to identify asbestos-content before disturbing the tiles.

4. Asbestos Cement Panels, Window/Door Caulking and Glazing Compounds

a) Maintain asbestos cement panels and window/door caulking and glazing compounds in undamaged condition.

5. <u>Carpet Glue, Blackboard/Tack Board Glue, Floor Tile Mastic, Cove Base, and Mastic</u>

- a) Reduce the likelihood of fiber release by leaving materials in place.
- b) Maintain materials in good condition. Collect samples and analyze to identify asbestos-content before disturbing.

F:\P2020\1149\A10\Deliverables\Report\3 Year Re-Inspection 2021\Tashua\Tashua ES_Final.docx



Appendix F

Asbestos Inspector and Management Planner State Licenses and EPA Accreditations

1005448 SP

1564

-C01 P05455-I



JAMES B BLUM **FUSS & O'NEILL LLC** 146 HARTFORD RD **MANCHESTER CT 06040-5992**

Dear JAMES B BLUM,

Attached you will find your validated certificate for the coming year. Should you have any questions about your certificate renewal, please do not hesitate to write or call:

Department of Public Health P.O. Box 340308 M.S.#12MQA Hartford, CT 06134-0308

(860) 509-7603 oplc.dph@ct.gov www.ct.gov/dph/license

Sincerely,

DEIDRE S. GIFFORD, MD, MPH, ACTING COMMISSIONER DEPARTMENT OF PUBLIC HEALTH

STATE OF CONNECTICUT

DEPARTMENT OF PUBLIC HEALTH

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT

THE INDIVIDUAL NAMED BELOW IS CERTIFIED BY THIS DEPARTMENT AS A

ASBESTOS CONSULTANT-INSPECTOR

JAMES B BLUM

CERTIFICATE NO

000841

CURRENT THROUGH 11/30/21

VALIDATION NO 03-856192

EMPLOYER'S COPY

STATE OF CONNECTICUT DEPARTMENT OF PUBLIC HEALTH

NAME

JAMES B BLUM

VALIDATION NO. 03-856192

CERTIFICATE NO.

CURRENT THROUGH 11/30/21

000841

PROPESSION ASBESTOS CONSULTANT-INSPECTOR

INSTRUCTIONS:

VALIDATION NO

03-856192

- 1. Detach and sign each of the cards on this form
- 2. Display the targe card to a prominent place in your office or place of business.
- 3. The wallet card is for you to carry on your person. If you do not wish to carry the wallet eart, place it in a secure place.
- 4. The employer's capy is for persons who must domonstrate current licensure/certification in order to retain employment or privileges. The employer's card is to be presented to the employer and kept by them as a part of your personnel file. Only one copy of this card can he supplied to you.

WALLET CARD

STATE OF CONNECTICUT DEPARTMENT OF PUBLIC HEALTH

NAME

JAMES B BLUM

CERTIFICATE NO.

CURRENT THROUGH 11/30/21

000841 PROFESSION

ASSESTOS CONSULTANT-INSPECTOR

CERT#: A-509-V692

CHEMSCOPE TRAINING DIVISION

ASBESTOS INSPECTOR REFRESHER 4-HOUR TRAINING CERTIFICATE

James Blum

146 Hartford Road, Manchester CT

Has attended a 4-hour annual refresher course on the subject discipline on

9/1/2020 and has passed a written examination.

"The person receiving this certificate has completed the requisite training for asbestos accreditation as an inspector under TSCA Title II"

systems, planning, inspecting for asbestos, sampling and analysis, respiratory protection, government regulations and preparing the Course topics include a review and update on asbestos health hazards, functions of inspectors and management planners, building inspection report.

This training course has been accredited by the State of Connecticut.

Examination Score: 88%

Exam Date: 9/1/2020

Expiration Date: 9/1/2021

Daniel Sullivan Training Manager

Chem Scope, Inc. 15 Moulthrop Street North Haven CT 06473 Phone: 203.865.5605 www.chem-scope.com

Litho in U.S.A. @ GOES 340

004489-0004511-006600 i of 0006001-C01-a1d00101-0564-04505

EDUARDO M. MARQUES

0564 COLP04505 (

EDUARDO M. MARQUES

MANCHESTER CT 06040

1(804.199 SP

FUSS & ONEILL ENVIRO SCIENCE LLC 146 HARTFORD ROAD

Dear EDUARDO M. MARQUES.

Attached you will find your validated certificate for the coming year. Should you have any questions about your certificate renewal, please do not hesitate to write or call:

Department of Public Health (860) 509-7603 P.O. Box 340308 oplc.dph@ct.gov M.S.#12MQA www.ct.gov/dph/license

Sincerely,

Hartford, CT 06134-0308

DEIDRE S. GIFFORD, MD, MPH, ACTING COMMISSIONER

DEPARTMENT OF PUBLIC HEALTH

STATE OF CONNECTICUT

DEPARTMENT OF PUBLIC HEALTH PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT

THE INDIVIDUAL NAMED BELOW IS CERTIFIED

BY THIS DEPARTMENT AS A ASBESTOS CONSULTANT-INSP/MGMT PLANNER

CERTIFICATE NO

000201

CURRENT THROUGH

02/28/22

VALIDATION NO. 03-866767

EMPLOYER'S COPY

STATE OF CONNECTICUT DEPARTMENT OF PUBLIC HEALTH

NAME EDUARDO M. MARQUES

VALIDATION NO. 03-866767

CERTIFICATE NO.

CURRENT THROUGH 02/28/22

000201

PROFESSION ASBESTOS CONSULTANT-INSP/MGMT PLANNER

SIGNATURE

- INSTRUCTIONS:
- 1. Detach and sion each of the cards on this form
- . Display the large card in a prominent place in your office or place of business. 3. The reallel eard is for you to carry on your person, If you do not wish to carry the wallet
- card, place it in a secure place. 4. The employer's copy is for persons who must demonstrate current licensure/vertification in order to retain employment or privileges. The employer's card is to be presented to the employer and kept by them as a part of your personnel file. Only one copy of this card can

CERT#: A-508-V587

CHEMSCOPE TRAINING DIVISION

. .

ASBESTOS INSPECTOR/MANAGEMENT PLANNER REFRESHER

8-HOUR TRAINING CERTIFICATE

Eduardo Miguel Marques

146 Hartford Road, Manchester CT

Has attended an 8-hour course on the subject discipline on

8/14/2020 and has passed a written examination.

"The person receiving this certificate has completed the requisite training required for asbestos accreditation as an inspector/management planner under TSCA Course topics include a review and update on asbestos health hazards, functions of inspectors and management planners, building systems, Title II"

planning, inspecting for asbestos, sampling and analysis, respiratory protection, government regulations and preparing the inspection report.

The training course has been accredited by the State of Connecticut.

Examination 1 Score: 86%

Examination 2 Score: 88% Exam Date: 8/14/2020

Expiration Date: 8/14/2021

Training Manager Daniel Sullivan

North Haven CT 06473 www.chem-scope.com Phone: 203.865.5605 15 Moulthrop Street Chem Scope, Inc.

Litho in U.S.A. @ GOES 340