Asbestos Hazard Emergency Response Act Three-Year Asbestos Re-Inspection and Management Plan Update

for

Jane Ryan Elementary School

(Title 40 CFR, Part 763, Subpart E)

For Compliance with State of Connecticut Department of Public Health Asbestos-Containing Material in Schools Regulation (Sections 19a - 333-1 through 19a - 333-13) and EPA Asbestos Hazard Emergency Response Act

Trumbull Public Schools

Trumbull, Connecticut

February 2021



56 Quarry Road Trumbull, CT 06611



May 3, 2021

Mr. Paul Hendrickson Business Office – Business Administrator Trumbull Public Schools 6254 Main Street Trumbull, CT 06611

RE: Three-Year AHERA Asbestos Re-Inspection and Management Plan Update

Re-Inspection Date: February 19, 2021

Jane Ryan Elementary School 190 Park Lane, Trumbull, CT

Fuss & O'Neill Project No. 20201149.A10

Dear Mr. Hendrickson:

Enclosed is the three-year AHERA Asbestos Re-Inspection and Management Plan Update report prepared by Fuss & O'Neill, Inc. at the Jane Ryan Elementary School located at 190 Park Lane in Trumbull, Connecticut (the "Site"). The inspection was performed for the Trumbull Public Schools (the "Client"). This report is an important document that must be kept on file at the school as well as at a central location where the Management Plans are maintained.

If you should have any questions regarding this report, please do not hesitate to contact me. Thank you for this opportunity to have served your environmental needs.

Sincerely,

56 Quarry Road Trumbull, CT 06611 † 203.374.3748 800.286.2469 Eduardo Miguel Marques Senior Environmental Analyst

EMM/nw

f 203.374.4391 www.fando.com

Enclosure

California

Connecticut

Maine

Massachusetts

New Hampshire

Rhode Island

Vermont

F:\P2020\1149\A10\Deliverables\Report\3 Year Re-Inspection 2021\Jane Ryan\Jane Ryan ES_Final.docx



Table of Contents

Asbestos Hazard Emergency Response Act Three-Year Re-Inspection and Management Plan Update Jane Ryan Elementary School

Security	1.1 1.2 1.3	Duction
2	Buildi	ng and Mechanical System Description3
3	Three 3.1	Year Re-Inspection
4	Re-In: 4.1 4.2 4.3 4.4	Review of Existing Records
5	Mana 5.1 5.2 5.3 5.4	gement Plan Update
6	EPA A	ccreditation Requirements9
Appei	ndices	End of Report
APPEN APPEN APPEN APPEN	NDIX A NDIX B NDIX C NDIX D NDIX E NDIX F	EXISTING RECORDS CHECKLIST RE-INSPECTION FORM 1A RE-INSPECTION FORM 2 SAMPLE 6-MONTH PERIODIC SURVEILLANCE FORM PREVENTIVE MEASURES ASBESTOS INSPECTOR AND MANAGEMENT PLANNER STATE LICENSES AND EPA ACCREDITATIONS



1 Introduction

1.1 Background

The Clean Air Act required the United States Environmental Protection Agency (EPA) to develop standards to address the potential health risks associated with adverse effects of asbestos exposure as an indoor contaminant. In October 1986, the EPA promulgated the Asbestos Hazard Emergency Response Act (AHERA) located at Title 40 CFR, Part 763, Subpart E.

The AHERA regulations required that local education agencies (LEAs) conduct inspections of each school building that they lease, own, or otherwise use as a school building to identify friable (easily crumbled or crushed to powder by hand pressure) and non-friable asbestos-containing building materials (ACBM) locations. The original inspections were required to have been completed prior to October 12, 1988.

AHERA also requires that any building leased or acquired on or after October 12, 1988 that is to be used as a school building shall be inspected for friable and non-friable ACBM prior to use as a school building. In the event of an emergency use of a building that has not been inspected for ACBM, the building shall be inspected within 30 days after commencement of such use.

The regulatory requirements remain in effect for private or public school systems, a church-affiliated school of any denomination, a school dedicated to the education of children with special needs, or a charter school. In the State of Connecticut, the Department of Public Health (CTDPH) is responsible for AHERA regulation enforcement.

1.2 Local Education Agency (LEA) Responsibilities

- A. The LEA is responsible for compliance with the AHERA regulation. The following responsibilities must be followed:
 - 1. The LEA must designate a person to ensure that all of the AHERA requirements are properly implemented. The Designated Person must receive adequate training to perform their duties.
 - The LEA must ensure that management plans are maintained in a central location, as well as at each facility, and such plans and records are available for inspection or review at all times.
 - The LEA must inform all workers, building occupants or their legal representative in writing at least once per school year about asbestos-related activities, and the availability of the AHERA management plans for the school buildings.



- 4. The LEA must ensure proper accreditation for all persons who perform asbestos inspections, asbestos re-inspections, develop/update management plans, develop response actions, and perform required response actions including operations and maintenance (O&M) activities that may disturb asbestos.
- 5. The LEA must provide training for all custodial and maintenance staff who regularly perform building maintenance where ACBM are present. The training must be provided upon initial hire, as well as annual updates.
- The LEA must provide information (disclosure) to any workers who may perform work and may come into contact with asbestos in school buildings where ACBM or presumed ACBM are present.
- 7. The LEA must ensure that known ACBM or presumed ACBM are provided with warning labels in routine maintenance areas.
- 8. The LEA must ensure that periodic surveillance is performed at least once every six months, after management plan implementation, in all school buildings that it leases, owns, or otherwise uses that contains ACBM or presumed ACBM.
- 9. The LEA must ensure that once every three years, after a management plan is implemented, a Re-Inspection is performed at each school building that it leases owns or otherwise uses that contains ACBM or presumed ACBM.

Refer to above-mentioned regulation for full requirements and responsibilities.

1.3 Accreditation

A. Local Education Agency (LEA):

LEA:

Trumbull Public Schools

Address:

6254 Main Street

Trumbull, CT

Phone:

(203) 452-4300

B. Designated Person:

Designated Person:

Mr. Paul Hendrickson

Address:

6254 Main Street

Trumbull, CT

Phone:

(203) 452-4300



C. Asbestos Consultant:

Firm: Fuss & O'Neill, Inc. Address: 56 Quarry Road

Trumbull, CT

Phone: (203) 374-3748 Fax: (203) 374-4391

D. Asbestos Inspector:

Inspector: James B. Blum

CTDPH License #: 000841 Expiration Date: 11/30/2021

E. Asbestos Management Planner:

Planner: Eduardo Miguel Marques

CTDPH License #: 000201 Expiration: 2/28/2022

2 Building and Mechanical System Description

The original Jane Ryan Elementary School is a one-story building and was reportedly constructed in 1955. The building contains approximately 50,000 square feet (SF) of total floor area. The building is heated by a gas-fired hot water and rooftop heating, ventilating and air conditioning (HVAC) units. According to information available from the Client, there have been multiple floor tile replacement projects which occurred since 2015. The building also had exterior windows and associated cementitious panels abated during the summer of 2019.

3 Three Year Re-Inspection

3.1 Re-Inspection Procedures

This three-year asbestos re-inspection was conducted in accordance with EPA requirements of the AHERA regulation, Title 40 CFR, Part 763, Section 763.85 (b).

On February 19, 2021, Fuss & O'Neill, Inc. (Fuss & O'Neill) representative Mr. James B. Blum performed the re-inspection.

- A. During the re-inspection, Fuss & O'Neill conducted the following required tasks:
 - 1. A visual re-inspection and reassessment of all known friable or assumed ACBM.
 - 2. A visual re-inspection of ACBM that was previously considered non-friable to determine if the present condition of the material has become friable.



3. Identification and assessment of any newly-identified homogeneous area that contains friable ACBM since the last inspection or re-inspection.

4 Re-Inspection Report

4.1 Review of Existing Records

An important part of this AHERA re-inspection involved researching prior documentation that is required to be present at the school, as well as at the central recordkeeping location where management plans are stored.

Please see Appendix A for the checklist for existing records.

4.2 Re-Inspection Summary

The on-site portion of the re-inspection was documented on forms modeled after examples provided by the EPA and reviewed with the CTDPH. The first form, **Re-Inspection Form 1A**, identifies previous inspection data gathered during the initial AHERA inspection and subsequent re-inspection (see Appendix B). This form is useful to reference response actions (if any), which have been performed since the last inspection, as well as identifies the last known conditions of ACBM in the building. It additionally provides the inspector a "quick glance" reference when performing the re-inspection.

The third EPA form, **Re-Inspection Form 2**, was used to provide information and justification regarding <u>re-assessment of the ACBM</u> (see *Appendix C*). This form also provides response action recommendations, including a tentative schedule for completing response actions that recommend removal or repair.

No bulk samples were collected during this re-inspection.

Using EPA protocol and criteria, the following materials existing in Jane Ryan Elementary School at the time of this three-year re-inspection have been determined and/or assumed to be **ACBM**. Please refer to the above-mentioned Re-Inspection Forms for specific locations of the materials.



Table 1
Asbestos-Containing Building Materials

	Asbestos-Cont	aining Building Ma		
Material	Location	Reference	Asbestos Content	Notes
D 1 D1 40!! 40!! F1	Rooms 1, 4, 5, 7,	EnviroMed 2015		
Dark Blue 12"x12" Floor	10C, 13, 15, 16, 16B,	AHERA 3-Year	Assumed	
Tile & associated Adhesive	16C	Re-Inspection		
White with Gray 12"x12"		EnviroMed 2015		
Floor Tile & associated	Rooms 16A, 16D	AHERA 3-Year	Assumed	
Adhesive		Re-Inspection		
White with Black Specks, Red, and Green 12"x12" Floor Tile & associated Adhesive (Checkboard Pattern)	Hallways, Cafeteria	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
Light Blue 12"x12" Floor Tile & associated Adhesive	Rooms 2, 10A, 10B	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed	
White with Green 12"x12"		EnviroMed 2015		
Floor Tile & associated	Room 11	AHERA 3-Year	Assumed	
Adhesive	Room 11	Re-Inspection	Assumed	
	Rooms 1, 4, 5, 7,	EnviroMed 2015		
Blue 4" Cove Base &	10C, 13, 15, 16, 16A,	AHERA 3-Year	Assumed	
associated Adhesive	16B, 16C, 16D	Re-Inspection	7133uiiled	
	Sprinkler Room,	EnviroMed 2015		
Pipe Insulation & Pipe	Mechanical Room by	AHERA 3-Year	Assumed	
Fitting Insulation	Gym	Re-Inspection	1100011111111	
Thinset & Grout associated	Girls' and Boys'	EnviroMed 2015		
with Ceramic Tile (multiple	Bathrooms, Faculty	AHERA 3-Year	Assumed	
colors and sizes)	Bathrooms	Re-Inspection		
		EnviroMed 2015		
Thinset & Grout associated	Kitchen	AHERA 3-Year	Assumed	
with Quarry Tile		Re-Inspection		
		EnviroMed 2015		
Black Sink Undercoat	Rooms 4, 5, 17 - 23	AHERA 3-Year	Assumed	
		Re-Inspection		***
	Administration	EnviroMed 2015		
Carpet Adhesive	Offices, Media	AHERA 3-Year	Assumed	Address of the second
	Center	Re-Inspection		
Adhesive associated with		EnviroMed 2015		
Adnesive associated with Chalkboard and Tackboard	Rooms 1 - 20	AHERA 3-Year	Assumed	
CHAIKDOALU AHU TACKDOALU		Re-Inspection		and development of the control of th
With with Red and Blue		EnviroMed 2015		
Streaks Sheetflooring &	Nurse's Office	AHERA 3-Year	Assumed	La company de la
associated Adhesive		Re-Inspection	The second secon	



Mr. Eduardo Miguel Marques reviewed the information obtained during this Re-Inspection. Mr. Marques is an EPA-accredited and CTDPH-licensed Asbestos Management Planner.

4.3 Newly Identified or Re-sampled ACBM Materials

During this re-inspection, no newly identified asbestos-containing materials or assumed ACBM were observed. Previously identified ACM exterior window caulk has been abated in 2019.

AHERA regulations pertain to interior identified or assumed ACBM and limited exterior ACBM. AHERA regulations do include ACBM located on exterior porticos, covered walkways, and mechanical equipment used to condition interior building air.

Any suspect material encountered during renovation/demolition/maintenance activities that is not specifically identified in the Asbestos Management Plan (AMP) as a non-ACM should be assumed to contain asbestos unless sample results indicate otherwise.

Additional Information:

- ACBM floor tile and associated mastics may exist below non-moveable objects such as cabinets.
 platforms, sheetrock walls, lockers, etc.;
- Samples of exterior building materials not covered under AHERA, such as caulking and glazing
 compounds, roofing materials and materials behind exterior walls and panels should be
 collected and analyzed to determine asbestos content prior to performing activities that would
 disturb them;
- Asbestos-containing vapor barriers and waterproofing materials may exist beneath wood floors, behind walls, exterior below ground surface foundations, etc.; and
- Subsurface cementitious pipe (i.e., asbestos cement pipe).

4.4 Physical Assessment of ACBM

During inspection, suspect ACBM were separated into three EPA categories. These categories are thermal system insulation (TSI), surfacing ACBM, and miscellaneous ACBM. TSI includes all materials used to prevent heat loss or gain or water condensation on mechanical systems. Examples of TSI are pipe and fitting insulations, boiler insulation, and duct insulation. Surfacing ACBM is commonly used for fireproofing, decorative, and acoustical applications. Miscellaneous materials include all ACBM not listed in TSI or surfacing, such as sheet flooring, vinyl asbestos flooring, ceiling tiles, and construction mastics/adhesives.

Finally, ACBM were quantified in linear and/or square feet, depending on the nature of the material.

The ACBM identified during the inspection and still remaining in the school were re-assessed using the CTDPH and AHERA guidelines for assessment of ACBM. The following assessment categories are listed:



- 1. Damaged or significantly damaged TSI ACBM
- 2. Damaged friable surfacing ACBM
- 3. Significantly damaged friable surfacing ACBM
- 4. Damaged or significantly damaged friable miscellaneous ACBM
- 5. ACBM with potential for damage
- 6. ACBM with potential for significant damage
- 7. Any remaining friable ACBM or friable suspected ACBM

Material locations, assessments, and recommended response actions are listed in the Re-Inspection forms.

5 Management Plan Update

5.1 Recommended Response Actions

Based on the inspection report, physical walk-through inspection, and existing ACBM conditions, the following response actions are recommended:

- Removal Not Applicable
- 2. Repair Not Applicable
- 3. Enclosure Not Applicable
- 4. Encapsulation Not Applicable
- 5. Operations and Maintenance (O & M) Repair one (1) pipe fitting insulation in Sprinkler Room. All remaining ACBM.

It should be noted that only ACBM with assessments of 1 or 2 are recommended for removal or repair. The remaining ACBM should be included in the O & M Program. The condition of these ACBM will be monitored until all of the ACBM have been completely removed from the building. A successful O & M Program includes the following elements:

- A. <u>Cleaning</u>: All areas of the school where friable ACBM or assumed friable ACBM are present should be cleaned at least once after completion of the initial inspection. Additional cleaning may be necessary if the Management Planner makes a written recommendation indicating the methods and frequency of such cleaning.
- B. O & M Activities: The LEA shall ensure that the procedures described below are followed to protect building occupants from O & M activities that may disturb known or assumed ACBM:
 - 1. Restrict entry into the area either by physically isolating or by scheduling.
 - 2. Post asbestos warning signs to prevent entry by unauthorized persons.
 - 3. Deactivate or temporarily shut off or divert the air-handling system to the area.
 - Use proper work practices and engineering controls, such as wet methods, protective clothing, High Efficiency Particulate Air (HEPA) vacuums, mini-enclosures/glove bags, etc. to inhibit fiber migration.
 - 5. Place asbestos debris and other contaminated materials into a sealed, leak-tight container for disposal.



- C. <u>Minor Fiber Release Episode</u>: The LEA shall ensure that the procedures described below are followed in the event of a minor fiber release episode (i.e., disturbance of less than or equal to 3 linear/square feet of friable ACBM):
 - 1. Saturate the debris using wet method.
 - 2. Place the debris in a sealed, leak-tight container and clean the area.
 - Repair the area of damaged ACBM with materials such as asbestos-free spackling, plaster or insulation or seal with an encapsulant.
- D. <u>Major Fiber Release Episode</u>: The LEA shall ensure that the procedures described below are followed in the event of a major fiber release episode (i.e., disturbance of greater than 3 linear/square feet of friable ACBM):
 - 1. Restrict entry into the area and post asbestos warning signs.
 - 2. Deactivate or temporarily shut off or divert the air handling system from the area to prevent fiber migration.
 - 3. The response action for any major fiber release episode must be prepared by EPA-accredited Asbestos Project Designers and conducted by EPA-accredited personnel.
 - 4. The LEA shall notify the CTDPH of any major fiber release episode within twenty-four hours of its occurrence and, if necessary, provide written notification as required by applicable federal and/or state regulations.

5.2 Periodic Surveillance

At least once every six months after an AMP is implemented, the LEA will conduct periodic surveillance in the school that contains ACBM or assumed ACBM. The person conducting periodic surveillance will visually inspect all areas in the school that where ACBM have been identified in the AMP, record the date of surveillance, their name, any changes in the ACBM condition and submit the record to the LEA Designated Person for inclusion in the AMP.

Please see *Appendix D* for the sample Periodic Surveillance Form that may be used for conducting periodic surveillance.

5.3 Preventive Measures

The LEA shall institute appropriate preventive measures to eliminate the reasonable likelihood that ACBM will become damaged, deteriorated, or delaminated.

Please see Appendix E for preventive measures designed for various types of ACBM that may exist in the school.

5.4 Abatement (Removal) Cost Estimates

At the time of the February 19, 2021 re-inspection, no materials were observed to be damaged (other than O&M repairs); therefore, estimated abatement costs have not been provided.



6 EPA Accreditation Requirements

The EPA accreditations and the CTDPH Asbestos Inspector for James B. Blum and Eduardo Miguel Marques are provided in *Appendix F*.

Report prepared by Senior Environmental Technician James B. Blum, CMC.

Reviewed by:

Eduardo Miguel Marques

Senior Environmental Analyst

Jared D. Smith, CSP

Senior Project Manager



Appendix A

Existing Records Checklist



Existing Records Checklist

Local Education Agency (LEA): Trumbull Public Schools

6254 Main Street Trumbull, CT 06611

School Building: <u>Jane Ryan Elementary School</u>

The following documentation is required to be present in both the LEA's office, as well as in a centralized location in the school administrative office. The information included in this checklist will be verified to be present and complete as part of three-year Re-Inspection.

		roc	ATION
	DOCUMENTATION	School	LEA Office
1	Original AHERA Operations and Maintenance Plan/Inspection Report	No	No
2	Three Year Re-Inspection (First and All Subsequent Inspections)	No	Limited*
3	Parents and Teachers Notifications (Annually Since Last Re- Inspection)	Yes	Yes
4	Designated Person Identification and Proper Training (Person Must Be Named and Have Appropriate Training)	No	No
5	Designated Person Periodic Surveillance (Once Every Six Months)	No	Limited*
6	Maintenance Staff Awareness Training Records	No	No
7	Outside Vendor Awareness Notification	No	No
8	Asbestos Warning Signs and Labels (Required Posting in Boiler Rooms and Mechanical Spaces Only)	No	No
9	Response Action Records (Includes Any Abatement Conducted Since Last 3-Year Re-Inspection)	No	No

Comments: Items marked "No" indicate not present/available at the time of this inspection.
*Note: LEA office found to contain only records of 2015 3-year re-inspection, and 6 month surveillance conducted in 2015. Information associated with abatement work reportedly performed at the Site was not present.

Inspector (LEA Office): <u>James B. Blum</u> Date: <u>February 23, 2021</u>

Inspector (School): <u>James B. Blum</u> Date: <u>February 19, 2021</u>



Appendix B

Re-Inspection Form 1A



Re-Inspection Form 1(A) - List of Identified ACBM

School: <u>Jane Ryan Elementary School</u> Address: <u>190 Park Lane, Trumbull, CT</u>

Date(s) of Original Inspection: <u>Unknown</u>
Date(s) of Subsequent Re-Inspections: <u>2015, 2021</u>

Hor	nogeneous Mai	erial	Material Assessme				Response Actions	
Sample Number	Asbestos Content	Material Description	Category	Friability	Assessment Category (1-7)	Recorded Locations	Taken/Renovations/Other Comments	
N/A	Assumed	Dark Blue 12"x12" Floor Tile & associated Adhesive	Misc.	NF	5	Rooms 1, 4, 5, 7, 10C, 13, 15, 16, 16B, 16C	Comments	
N/A	Assumed	White with Gray 12"x12" Floor Tile & associated Adhesive	Misc.	NF	5	Rooms 16A, 16D		
N/A	Assumed	White with Black Specks, Red, and Green 12"x12" Floor Tile & associated Adhesive (Checkboard Pattern)	Misc.	NF	5	Hallways, Cafeteria		
N/A	Assumed	Light Blue 12"x12" Floor Tile & associated Adhesive	Misc.	NF	5	Rooms 2, 10A, 10B		
N/A	Assumed	White with Green 12"x12" Floor Tile & associated Adhesive	Misc.	NF	5	Room 11		
N/A	Assumed	Blue 4" Cove Base & associated Adhesive	Misc.	NF	5	Rooms 1, 4, 5, 7, 10C, 13, 15, 16, 16A, 16B, 16C, 16D		
N/A	Assumed	Pipe Insulation & Pipe Fitting Insulation	TSI	F	5	Sprinkler Room, Mechanical Room by Gym		
N/A	Assumed	Thinset & Grout associated with Ceramic Tile (multiple colors and sizes)	Misc.	NF	5	Girls' and Boys' Bathrooms, Faculty Bathrooms		
N/A	Assumed	Thinset & Grout associated with Quarry Tile	Misc.	NF	5	Kitchen		
N/A	Assumed	Black Sink Undercoat	Misc.	NF	5	Rooms 4, 5, 17 - 23	***************************************	
N/A	Assumed	Carpet Adhesive	Misc.	NF	5	Administration Offices, Media Center		
N/A	Assumed	Adhesive associated with Chalkboard and Tackboard	Misc.	NF	5	Rooms 1 - 20	**************************************	



Ho	Homogeneous Material			Homogeneous Material Material Ass						Response Actions
Sample Number	Asbestos Content	Material Description	Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Taken/Renovations/Other Comments			
N/A	Assumed	With with Red and Blue Streaks Sheetflooring & associated Adhesive	Misc.	NF	5	Nurse's Office				
N/A	Assumed	9"x9" Floor Tile & Mastic	N/A	N/A	N/A	Rooms 3, 7, 17 - 24, Book Storage Room, Storage Rooms, Gym Office, Music Room	Material has been reported to have been abated over several phases after 2015. Materials were not observed during this re-inspection			
JR053JR02A; JR0530JR05A	<1% - 7% Chrysotile	Window Caulk and Glazing	N/A	N/A	N/A	Throughout Exterior of Building	Material was abated during Summer 2019			
JR053JR03A	25% Chrysotile	Exterior Cementitious Panel	N/A	N/A	N/A	Throughout Exterior of Building	Material was abated during Summer 2019			
JR053JR10A-B	ND	2'x2' Suspended Ceiling Tiles (Multiple types: slots w/ pinholes, pinholes)	N/A	N/A	N/A	Throughout Building	Material was determined to be Non- ACBM; will be removed from the AMP			
JR053JR11A	75% Chrysotile	Black Paper Damp Proofing	N/A	N/A	N/A	Throughout Exterior of Building around windows	Material was abated during Summer 2019; Material may exists behind exterir brick façade			

Information abstracted by: <u>James B. Blum</u>

Date: February 19, 2021

 $Material\ Category;\ TSI = Thermal\ System\ Insulation,\ S = Surfacing,\ M = Miscellaneous$

LF = Linear Feet; SF = Square Fee

Friability: F = Friable, NF = Non-Friable

AHERA Assessment Categories: 1 = Damaged or significantly damaged TSI ACBM; 2 = Damaged friable surfacing ACBM; 3 = Significantly damaged friable surfacing ACBM; 4 = Damaged or significantly damaged friable miscellaneous ACBM; 5 = ACBM with potential for damage; 6 = ACBM with potential for significant damage; 7 = Any remaining friable ACBM or friable suspected ACBM



Appendix C

Re-Inspection Form 2



School:

Jane Ryan Elementary School

Date of Re-Inspection:

February 19, 2021

Homogeneous Material:

Dark Blue 12"x12" Floor Tile & associated Adhesive

Sample 1D:

 N/Δ

Estimated	Assessment				
ability Quantity	Category	Physical Description	Recommended Response Action(s)	Date Action Completed	
NF 4,000 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing	
P No			Date of Management Planner Review:	4/22/2021	
es B. Blum			Management Planner Name:	Eduardo Miguel Marques	
j Sungir Hiss.			Management Planner Signature:	ands Will Migh-	
341/CT			Accreditation #/State:	000201/CT	
30/2021			Expiration Date:	2/28/2022	
3	NF 4,000 SF No ss B. Blum	NF 4,000 SF 5 No SS B. Blum	NF 4,000 SF 5 ACBM with potential for damage? No SEB. Blum	NF 4,000 SF 5 ACBM with potential for damage Action(s) ACBM with potential for damage Accommend sampling to determine asbestos content prior to disturbance Date of Management Planner Review: Management Planner Name: Management Planner Signature: Accreditation #/State:	



School:

Jane Ryan Elementary School

Date of Re-Inspection:

February 19, 2021

Homogeneous Material:

White with Gray 12"x12" Floor Tile & associated Adhesive

Sample ID:

N/A

	ACBM RE-IN	MANAGEMENT PLANNER	RECOMMENDATIONS			
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 16A, 16D	NF	800 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	lected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	أسر	agaga Jillia .			Management Planner Signature:	ands Objet Nep-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021			~ ·	Expiration Date:	2/28/2022



School:

Jane Ryan Elementary School

Date of Re-Inspection:

February 19, 2021

White with Black Specks, Red, and Green. 12"x12" Floor Tile & associated Adhesive. (Checkboard Pattern)

Homogeneous Material:

Sample ID:

N/A

	ACBM RE-IN	MANAGEMENT PLANNER	RECOMMENDATIONS			
ACBM Location(s) by Assessmen Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Hallways, Cafeteria	NF	8,000 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM co	llected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	p de la companya de	ango Plor			Management Planner Signature:	edunder Virjah MagD-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



School:

Jane Ryan Elementary School

Date of Re-Inspection:

February 19, 2021

Homogeneous Material:

Light Blue 12"s12" Floor Tile & associated Adhesive

N/A

	ACBM RE-IN:	MANAGEMENT PLANNER I	RECOMMENDATIONS			
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 2, 10A, 10B	NF	1,200 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	ected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blur	n			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	p e	ege Hir			Management Planner Signature:	rando Najal Najif-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021			Mar.	Expiration Date:	2/28/2022

Sample ID:



School:

Jane Ryan Elementary School

Date of Re-Inspection:

February 19, 2021

Homogeneous Material:

White with Green 12"x12" Floor Tile & associated Adhesive

Sample ID:

N/A

	ACBM RE-IN	MANAGEMENT PLANNER	RECOMMENDATIONS			
ACBM Location(s) by Assessmen Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Room 11	NF	400 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM co	llected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	والمتراس	aprigjer Hiller.			Management Planner Signature:	stude High Maj-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021			~	Expiration Date:	2/28/2022



School:

Jane Ryan Elementary School

Date of Re-Inspection:

February 19, 2021

Homogeneous Material:

Blue 4" Cove Base & associated Adhesive Sample ID:

ile ID:

N/A

	ACBM RE-II	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessi Category	ment Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 1, 4, 5, 7, 10C, 13, 15, 16, 16B, 16C, 16D	16A, NF	800 LF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACE	JM collected?	No			Date of Management Planner Review:	4/22/2021
Inspector's Name:	James B. Bl	nm			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	يتماني	ing His.			Management Planner Signature:	stude Might Might
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021	L			Expiration Date:	2/28/2022



School: Jane Ryan Elementary School Date of Re-Inspection:

February 19, 2021

Homogeneous Material: Pipe Insulation & Pipe Fitting Insulation Sample ID: N/A

Α	CBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Sprinkler Room, Mechanical Room by Gym	न	100 LF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM colle	ected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Bh	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	pi mining	arge flere.			Management Planner Signature:	eander Wijd Migh-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021			C	Expiration Date:	2/28/2022



School:

Jane Ryan Elementary School

Date of Re-Inspection:

February 19, 2021

Homogeneous Material:

Thinset & Grout associated with Ceramic Tile (multiple colors and sizes) Sample 1D:

N/A

	ACBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Girls' and Boys' Bathrooms, Faculty Bathrooms	NF	2,000 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	ected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	المر	gogge Ween			Management Planner Signature:	educate Objek Major-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



School:

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Homogeneous Material: Thinset & Grout associated with Quarry Tile Sample ID: N/A

Jane Ryan Elementary School

Д	CBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Complete
Kitchen	NF 800 SF 5 ACBM with potential for damage				Maintain under O & M Plan, Recommend sampling to determine Ongoing asbestos content prior to disturbance	
Were additional samples of this ACBM colle	ected?	Date of Management Planner Review:	4/22/20			
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:		Management Planner Signature:	Educate Object 1949-			
Accreditation #/State:	reditation #/State: 000841/CT					000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022

Date of Re-Inspection:

February 19, 2021



School: <u>Jane Ryan Elementary School</u>

Date of Re-Inspection:

February 19, 2021

Homogeneous Material:

Black Sink Undercoat

Sample ID:

N/A

	ACBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 4, 5, 17 - 23	NF	9 EA	5	ACBM with potential for damage	Not Regulated By AHERA; For Informational Purposes Only. Material Must Be Managed/Disposed Of As ACM Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	lected?	No			Date of Management Planner Review:	4/22/2021
Inspector's Name:	James B. Blu	ım			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	and the second	iarys flere.			Management Planner Signature:	stude Apil App
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



School: <u>Jane Ryan Elementary School</u> Date of Re-Inspection:

Homogeneous Material: <u>Carpet Adhesive</u> Sample ID: <u>N/A</u>

,	ACBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Administration Offices, Media Center	NF	2,000 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM col	lected?	Date of Management Planner Review:	4/22/2021			
Inspector's Name:	James B. Blu	ım			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	أستستر	arajo Julio .			Management Planner Signature:	ander Popel 1949-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022

February 19, 2021



School:

Jane Ryan Elementary School

Date of Re-Inspection:

February 19, 2021

Homogeneous Material:

Adhesive associated with Chalkboard and Tackboard

Sample ID:

 N/Δ

,	CBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 1 - 20	NF	800 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll	ected?	Date of Management Planner Review:	4/22/202			
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	أأشر	egype filoloxu			Management Planner Signature:	stude Wijd Migh-
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021			~	Expiration Date:	2/28/2022



School:

Jane Ryan Elementary School

Date of Re-Inspection:

February 19, 2021

Homogeneous Material:

With with Red and Blue Streaks Sheetflooring.
& associated Adhesive Sample 1D:

N/A

A	CBM RE-IN	MANAGEMENT PLANNER RECOMMENDATIONS				
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Nurse's Office	NF	400 SF	5	ACBM with potential for damage	Maintain under O & M Plan, Recommend sampling to determine asbestos content prior to disturbance	Ongoing
Were additional samples of this ACBM coll-	ected?	No			Date of Management Planner Review:	4/22/202
Inspector's Name:	James B. Blu	m			Management Planner Name:	Eduardo Miguel Marques
Inspector Signature:	ji da	grape Johnson			Management Planner Signature:	amia bigil llagt
Accreditation #/State:	000841/CT				Accreditation #/State:	000201/CT
Expiration Date:	11/30/2021				Expiration Date:	2/28/2022



Appendix D

Sample 6-Month Periodic Surveillance Form



Sample 6-Month Periodic Surveillance Form

Local Education Agency (LEA): Facility Address: Date of Surveillance:

Trumbull Public Schools Jane Ryan Elementary School, 190 Park Lane, Trumbull, CT

Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
Dark Blue 12"x12" Floor Tile & associated Adhesive	Rooms 1, 4, 5, 7, 10C, 13, 15, 16, 16B, 16C					
White with Gray 12"x12" Floor Tile & associated Adhesive	Rooms 16A, 16D					
White with Black Specks, Red, and Green 12"x12" Floor Tile & associated Adhesive (Checkboard Pattern)	Hallways, Cafeteria					
Light Blue 12"x12" Floor Tile & associated Adhesive	Rooms 2, 10A, 10B					
White with Green 12"x12" Floor Tile & associated Adhesive	Room 11					
Blue 4" Cove Base & associated Adhesive	Rooms 1, 4, 5, 7, 10C, 13, 15, 16, 16A, 16B, 16C, 16D					
Pipe Insulation & Pipe Fitting Insulation	Sprinkler Room, Mechanical Room by Gym					
Thinset & Grout associated with Ceramic Tile (multiple colors and sizes)	Girls' and Boys' Bathrooms, Faculty Bathrooms					
Thinset & Grout associated with Quarry Tile	Kitchen					
Black Sink Undercoat	Rooms 4, 5, 17 - 23					
Carpet Adhesive	Administration Offices, Media Center					
Adhesive associated with Chalkboard and Tackboard	Rooms 1 - 20					
With with Red and Blue Streaks Sheetflooring & associated Adhesive	Nurse's Office					

Conditions: $D = Damaged$; $F = Fair$; $G = Ge$ SF = Square Feet	ood; IA = Inaccessible; N/A = Not Applicable; SD = Signific	cant Damage;
Surveillance conducted by:		
1000	(print name)	(signature)
I, the LEA's Designated Person, have read an	id understood the findings noted above:	
PN-+	-	



Appendix E

Preventive Measures



Preventive Measures for Various Asbestos-Containing Building Materials

A. Surfacing Materials

"Surfacing Materials" means materials in a school building that are applied by spray, trowel, or otherwise applied to surfaces. These include sprayed-applied fireproofing materials on structural members, ceiling and wall plasters, or other materials applied to surfaces for acoustical, fireproofing, or other purposes.

Surfacing Materials are generally considered friable and can release asbestos fibers if damaged by impact, air erosion, vibration, and/or water intrusion. When properly implemented, the following procedures will reduce the potential for fiber release:

1. Sprayed-Applied Fireproofing

- a) Identify the materials and post warning signs on the laid-in or glued-in ceiling tile. If the decking is not covered, place the sign on the wall.
- b) Maintain the materials in intact state and undamaged condition. During winter, pigeons, squirrels and other rodents tend to roost in boiler/machine rooms and dislodge sprayed-applied fireproofing on the decking. Prevent such possibilities.
- Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, enclosure is a temporary solution. Encapsulation of damaged sprayed-on fireproofing material is not recommended.
- d) Train the custodial people who are responsible for care and maintenance of surfacing materials. <u>Please note that the repair/removal can only be performed by a licensed abatement contractor.</u>

2. <u>Ceiling and Wall Plasters</u>

- a) Identify the materials and post asbestos warning signs.
- b) Maintain the materials in intact state and undamaged condition. Avoid storing/stacking on/near the materials to reduce contact damage.
- c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, repair or enclosure is a temporary solution.
- d) Train the custodial people who are responsible for care and maintenance of surfacing materials.

B. Thermal System Insulation (TSI)

"Thermal System Insulation (TSI)" means insulating materials applied to pipes, pipe fittings, boilers, breechings, tanks, ducts, or other components to prevent process heat loss or gain, water condensation, or for other purposes (e.g., fire door insulation core).



TSI are generally considered friable ACBM. This means they can be easily damaged, increasing the potential for fiber release. When properly implemented, the following procedures will reduce the potential for fiber release:

1. <u>Boiler and Breeching Insulation</u>

- a) Identify the locations and label the boiler. Warning signs should be posted outside the boiler room.
- b) Reduce the likelihood of fiber release by ensuring that the insulation is not damaged. Avoid storing/stacking on/near the boiler to reduce contact damage.
- c) Maintain the insulation in intact state and undamaged condition. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
- d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Pipe, Pipe Fitting, Tank, Duct & Breeching Insulations

- a) Identify the locations and label the materials. Warning signs should be posted outside of rooms that have TSI materials.
- b) Reduce the likelihood of fiber release by ensuring that the materials are not damaged. Avoid storing/stacking near the materials to reduce contact damage.
- c) Maintain all TSI materials in intact state and undamaged condition. Inspect the protective jackets for damage. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
- d) Train the custodial people who are responsible for care and maintenance of TSI.

 Please note that the repair/removal can only be performed by a licensed abatement contractor.

C. Miscellaneous Materials

"Miscellaneous Materials" are the other ACBM in a school building that are not categorized as Surfacing Materials or TSI. These include floor tiles, floor tile and carpet mastics, gypsum wallboard and joint compound, ceiling tiles, glue daubs, asbestos cement panels, cove base and associated glue, window/door caulking and glazing compounds, etc. The following maintenance procedures are recommended for these materials:

1. <u>Vinyl Asbestos Floor Tiles (VAT)</u>

Vinyl Asbestos Floor Tiles (VAT) are considered non-friable, however routine maintenance procedures such as spray-buffing, burnishing, wet scrubbing, and stripping can generate asbestos fibers. Following procedures, when properly implemented, will reduce the potential of fiber release:



- a) Do not sand, grind, or abrade the tiles. Stripping of VAT should be done as infrequently as possible. When stripping becomes necessary, follow the appropriate work practices. <u>Never perform dry stripping</u>.
- b) During spray-buffing or burnishing the floor, operate the machine at the lowest workable speed and use the least abrasive pad. Use a wet mop for routine cleaning whenever possible.
- c) Routinely check whether chair and desk glides are in good condition and replace when necessary. Worn glides can gouge the floor and cause fiber release.
- d) Place carpets/floor mats in all entrances to reduce abrasion of floor tiles by sand and pebbles. During winter, have parking lots and walkways swept to the extent possible to avoid the tracking of salt and ice-melting compounds into the school by the students.
- e) Train the custodial people who are responsible for care and maintenance of VAT. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Wallboard and Joint Compound Assembly

- a) Since a number of different homogeneous assemblies may exist in a building, sheetrock/joint compound must be assumed to be ACBM unless sample results prove otherwise. If any specific areas are going to be disturbed, samples of the material in that area should be collected and analyzed.
- b) Reduce the likelihood of fiber release by avoiding cutting or drilling holes through the sheetrock panels.

3. <u>Ceiling Tile and Glue Daubs</u>

- a) Reduce the likelihood of fiber release by limiting access to the space above the ceiling tiles. Maintain the ceiling tiles in undamaged condition. Replace any damaged or water-stained tile.
- b) If the ceiling tiles are non-asbestos, collect samples and analyze the glue daubs to identify asbestos-content before disturbing the tiles.

4. Asbestos Cement Panels, Window/Door Caulking and Glazing Compounds

a) Maintain asbestos cement panels and window/door caulking and glazing compounds in undamaged condition.

5. Carpet Glue, Blackboard/Tack Board Glue, Floor Tile Mastic, Cove Base, and Mastic

- a) Reduce the likelihood of fiber release by leaving materials in place.
- b) Maintain materials in good condition. Collect samples and analyze to identify asbestos-content before disturbing.



Appendix F

Asbestos Inspector and Management Planner State Licenses and EPA Accreditations

1005448 SP

1564

-COL P05455-I



JAMES B BLUM FUSS & O'NEILL LLC 146 HARTFORD RD MANCHESTER CT 06040-5992

Dear JAMES B BLUM,

Attached you will find your validated certificate for the coming year. Should you have any questions about your certificate renewal, please do not hesitate to write or call:

Department of Public Health P.O. Box 340308 M.S.#12MQA Hartford, CT 06134-0308

(860) 509-7603 oplc.dph@ct.gov www.ct.gov/dph/license

Sincerely,

DEIDRE S. GIFFORD, MD, MPH, ACTING COMMISSIONER **DEPARTMENT OF PUBLIC HEALTH**

STATE OF CONNECTICUT

DEPARTMENT OF PUBLIC HEALTH

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUE

THE INDIVIDUAL NAMED BELOW IS CERTIFIED BY THIS DEPARTMENT AS A ASBESTOS CONSULTANT-INSPECTOR

JAMES B BLUM

CERTIFICATE NO

000841

CURRENT THROUGH

11/30/21

VALIDATION NO. 03-856192

EMPLOYER'S COPY

STATE OF CONNECTICUT DEPARTMENT OF PUBLIC HEALTH

NAME

VALIDATION NO 03-856192

JAMES B BLUM

CERTIFICATE NO 000841

CURRENT THROUGH 11/30/21

PROPESSION

ASBESTOS CONSULTANT-INSPECTOR

INSTRUCTIONS:

VALIDATION NO

03-856192

F--

- 1. Defach and sign each of the cards on this form
- Display the large card in a prominent place in your office or place of business.The wallet card is for you to carry on your person. If you do not wish to carry the wallet
- eard, place it in a secure place.

 4. The employer's copy is for persons who must demonstrate current licensure/certification. in order to retain employment or privileges. The employer's card is to be presented to the employer and kept by them as a part of your personnel file. Only one copy of this card con he supplied to you.

WALLET CARD

STATE OF CONNECTICUT DEPARTMENT OF PUBLIC HEALTH

NAME

JAMES B BLUM

CERTIFICATE NO.

CURRENT THROUGH 11/30/21

000841 PROFESSION

ASSESTOS CONSULTANT/INSPECTOR

CERT#: A-509-V692

CHEMSCOPE TRAINING DIVISION

ASBESTOS INSPECTOR REFRESHER 4-HOUR TRAINING CERTIFICATE

James Blum

146 Hartford Road, Manchester CT

Has attended a 4-hour annual refresher course on the subject discipline on

9/1/2020 and has passed a written examination.

"The person receiving this certificate has completed the requisite training for asbestos accreditation as an inspector under TSCA Title II"

systems, planning, inspecting for asbestos, sampling and analysis, respiratory protection, government regulations and preparing the Course topics include a review and update on asbestos health hazards, functions of inspectors and management planners, building inspection report.

This training course has been accredited by the State of Connecticut.

Examination Score: 88%

Exam Date: 9/1/2020 Expiration Date: 9/1/2021

Daniel Sullivan Training Manager

Chem Scope, Inc.
15 Moulthrop Street
North Haven CT 06473
Phone: 203.865.5605
www.chem-scope.com

@ GOES 340

Litho in U.S.A.

100000449 SP

0564

-C.01 P04505 £



EDUARDO M. MARQUES FUSS & ONEILL ENVIRO SCIENCE LLC 146 HARTFORD ROAD MANCHESTER CT 06040

Dear EDUARDO M. MARQUES,

Attached you will find your validated certificate for the coming year. Should you have any questions about your certificate renewal, please do not hesitate to write or call:

Department of Public Health P.O. Box 340308 M.S.#12MQA Hartford, CT 06134-0308

(860) 509-7603 oplc.dph@ct.gov www.ct.gov/dph/license

Sincerely,

DEIDRE S. GIFFORD, MD, MPH, ACTING COMMISSIONER

DEPARTMENT OF PUBLIC HEALTH

STATE OF CONNECTICUT

DEPARTMENT OF PUBLIC HEALTH

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT

THE INDIVIDUAL NAMED BELOW IS CERTIFIED BY THIS DEPARTMENT AS A

ASBESTOS CONSULTANT-INSP/MGMT PLANNER

CERTIFICATE NO.

EDUARDO M. MARQUES

000201

CURRENT THROUGH

02/28/22

VALIDATION NO.

03-866767

EMPLOYER'S COPY

STATE OF CONNECTICUT DEPARTMENT OF PUBLIC HEALTH

NAME

EDUARDO M. MARQUES

VALIDATION NO 03-866767

CERTIFICATE NO.

CURRENT THROUGH

02/28/22

000201 PROFESSION

AS@ESTOS CONSULTANT-INSP/MGMT PLANNER

SIGNATURE

Derider 5. S. ACTING COMMISSIONER

INSTRUCTIONS:

- 1. Detach and sion each of the cords on this form
- Display the large card in a prominent place in your office or place of business.
- 3. The wallet card is for you to carry on your person. If you do not wish to carry the wallet card, place it in a secure place.
- 4. The employer's copy is for persons who must demanstrate current licensure/certification in order to retain employment or privileges. The employer's card is to be presented to the employer and kept by them as a part of your personnel file. Only one copy of this card can

CERT#: A-508-V587

CHEMSCOPE TRAINING DIVISION

ASBESTOS INSPECTOR/MANAGEMENT PLANNER REFRESHER

8-HOUR TRAINING CERTIFICATE

Eduardo Miguel Marques

146 Hartford Road, Manchester CT

Has attended an 8-hour course on the subject discipline on

8/14/2020 and has passed a written examination.

"The person receiving this certificate has completed the requisite training required for asbestos accreditation as an inspector/management planner under TSCA

Course topics include a review and update on asbestos health hazards, functions of inspectors and management planners, building systems, planning, inspecting for asbestos, sampling and analysis, respiratory protection, government regulations and preparing the inspection report.

The training course has been accredited by the State of Connecticut.

Examination 1 Score: 86%

Examination 2 Score: 88% Exam Date: 8/14/2020

Expiration Date: 8/14/2021

Daniel Sullivan Training Manager

Chem Scope, Inc. 15 Moulthrop Street North Haven CT 06473 Phone: 203.865.5605 www.chem-scope.com

Litho in U.S.A. @ GOES 340